

United States Steel Corporation Clainton Works 400 State Street Clairton, PA 15025



February 6, 2006

Dr. Roger C. Westman Department of Air Quality Bureau of Air Pollution Control 301 Thirty-Ninth Street Pittsburgh, PA 15201

U.S. Environmental Protection Agency Region III Air, Radiation & Toxics Division 1650 Arch Street Philadelphia, PA 19103-2029 ATTN: James W. Hagedorn (3AT23)

Assistant Council Southwest Region 400 Waterfront Drive Pittsburgh, PA 15222-4745 ATTN: Steve Hepler

Department of Justice Department of Environmental Protection Environmental and Natural Resource Division Environmental Enforcement Section P.O. Box 7611 Ben Franklin Station Washington, D.C. 20044 ATTN: David Street, Esq.

Subject: USS Reference Number: 06-0038

ACHD Reference Number: N/A

100 Carbonate Unit USS Clairton Works

Gentlemen:

The attached form confirms our verbal report of the subject incident. Any questions concerning this matter should be referred to Coleen M. Davis at 233-1015.

Sincerely,

Anton Lukac Plant Manager Clairton Works

> RECEIVED (FEB 1 3 2006 Division Director (SAPOO)

NOTICE OF OUTAGE OF EQUIPMENT ARTICLE XXI - SECTION 2108.1

- 1. USS Reference Number: 06-0038
 ACHD Reference Number: N/A
- 2. Date & Time of Breakdown: Date: 02/01/06 Time: 2355 hours
- 3. Company Name: U.S. Steel Corporation USS Clairton Works
- 4. Specific Equipment Involved or Affected: 100 Carbonate Unit
- 5. BAPC Permit Number (if applicable):
- 6. Location: Clairton, PA
- 7. Nature and cause of breakdown: Intermittent operational problems occurred at the 100 Vacuum Carbonate Unit and coke oven gas was passed through the Sulfur Plant. The root cause was traced to a failed control valve in the rich carbonated solution service causing a temporary upset of the 100 Vacuum Carbonate Unit.
- 8. Identification of Emissions:
 - A. Type(s) (CO, NOX, SO_2 , Particulates, Hydrocarbons, etc.) Intermittent elevated H_2S in the down river gas line system, causing increased SO_2 at point of combustion.
 - B. Toxic qualities of each type (including its qualities as an irritant, and its potential for causing illness, disability, or mortality). SO₂ is an eye, nose, and throat irritant.
 - C. Amount of each type emitted (or likely to be emitted). Light
- 9. Measures taken (or to be taken) to minimize length of breakdown and amount of emissions, including shutdown or curtailment (or why it is impossible or impractical to do so).

 Operations by-passed the control valve. The 100 Carbonated Unit was stabilized at 0035 hours on 02/02/06 and the control valve is being operated manually until the automated valve can be replaced.
- 10. Facility back in operation Date: Time: hours

Signature Cless M. Acurs Date 3/7/06

Senior Environmental Control Engineer Phone: 233-1015